

4492

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 8611** Survey held at Sunderland Date Jan 5 1866
 107 on the Sea S. S. "Admiral Kanaris" Master Almond
 Tonnage 927 Built at Sunderland When built 1858
 By whom built James Laing Owners E. J. Gourley & Co.
 Port belonging to Sunderland Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock In dry dock

Last Survey, No. 2979 Port London Classed 9 A. 1
 (7.5.62) 11.62

REPAIRS

A strike of ceiling on each side removed, and the cement found good. Both surfaces of the plating exposed as per rule, and the iron found in good condition.

The outside has now received one coat of paint.

The owner was recommended to paint the plating, frames &c, inside, which has not yet been done.

Present Condition of the

Decks	Good	Tweenails	Keels	Good	Keelings, stuffed	Found good
Waterways	"	Breasthooks and Stemson	"	"	Windlass and Capstan	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Pumps	Good
Upper Deck Beams & Fastenings	"	Timbers of the Frames at the openings	"	"	Boats	Up in No
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Masts, Yards, &c.	"
Planksheers	"	Keelsons	"	"	Condition, how ascertained	Examined when practically well found Good
Sheerstrakes	"	Clamps and Shelves	"	"	Sails	3 B. 1 S. 2 K
Topsides	"	Ceiling	"	"	Anchors No. of	Complete
Wales	"	Rudder	Good	"	Cables	Good & sufficient
Plating (Bottom) and Counter	"	Copper	When put on	"	Hawsers and Warps	Good when as
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.				Standing & Running Rigging	Good

This ship is now in a good and efficient state of repair, fit for the conveyance of dry and perishable goods & and from all parts of the world, and eligible, in my opinion, to remain as classed 9 A. 1.

The Amount of Fee.....£ " : " : " is received by me.

Special..... 2 : 2 : "

Certificate (if required) " : " : "

Committee's Minute 30th January 1866.

Character assigned 9 A. 1
 (11.5.66)



© 2019

Lloyd's Register
 Foundation

ROJ439-0118