

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 494 Survey held at London Date 13th 622nd Dec^r 1865
 on the Iron Screw Ship "Lucerne" Master Jennell
 Tonnage 678 Built at Sunderland When built 1862
 By whom built Laird Owners fourley &c.
 Port belonging to Sunderland Destined Voyage Venice
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 4243 Port IRON. Classed 9. A. 1
 7.65

REPAIRS

Now done:-

The timber boards and ceiling, equal to one strake fore and aft, removed and both surfaces of outside plating examined in places. The cement was found sound and good and adhering satisfactorily to the Iron.

Painted the inside with Coal-tar, as high as the turn of Bilges, and above that with Red-lead paint. Scraped and painted the outside with Martins' Patent Paint.

Renewed one of the Sheer strake plates, and one of the Topside plates on the Starboard side, in consequence of damage.

Present Condition of the

Decks		Transoms, Rivets.		Windlass and Capstan	
Waterways	<u>Scrim.</u>	Breasthooks and Stems	<u>good</u>	Pumps	<u>good where seen.</u>
Comings	<u>good</u>	Transoms, Pointers, and Crutches	<u>good</u>	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>where</u>	Ditto Ditto at other places	<u>where</u>	Condition, how ascertained	<u>By enquiry & observation from the deck.</u>
Plank sheers		Keelsons		Sails	
Sheerstrakes one plate new	<u>seen.</u>	Clamps and Shelves	<u>seen.</u>	Anchors No. of	<u>good and sufficient</u>
Topsides one plate new		Ceiling		Cables	
Wales		Rudder Examined.		Hawsers and Warps	<u>where seen.</u>
Plank (Bottom) and Counter Painted		Copper Paint When put on	<u>now</u>	Standing & Running Rigging	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where seen.</u>				

She is now in good and efficient condition, and fit, in our opinion, to remain as classed, and to be marked (t.s. 1865) in the Register Book.

The Amount of Fee.....£ 2 : - : - is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 23rd January 1866

Character assigned 9 A 1 (t.s. 65)

record damage repair



© 2019

Lloyd's Register Foundation

IRON439-0138