

REPORT of SURVEY for REPAIRS.

Rev 16/4/66

No. in Reg. Book, **No. 9928** Survey held at L. Shields Date 16th March 18 66
 on the Iron Bk "Scutivania" Master J. Buchanan
 Tonnage 331 Built at Newcastle When built 1862
 By whom built Rogerson & Co Owners Cotton & Co
 Port belonging to Shields Destined Voyage Montreal
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 2945 Port Newcastle Classed 9 A. 1.

REPAIRS Annual Survey and for change of character to B.

Removed the ceiling in Hold from upper part of bilges upwards, and fitted the same into Hatches, for easy removal. Found the plating and frames quite free of oxidation, it having been removed a few months ago, and recoated, likewise beams stringers. Lifted some planks of ceiling in flat-catch side, found that the cement closely adhering to the skin plating. Plating floors and frames satisfactory. At present close, cleaned each peak and removed all oxidation therein from plating & angle irons, and scraped the outside skin plating from keel to gunwale, and recoated the same with Red lead & Patent paint. In

Present Condition of the peaks recoated with Red lead.

Decks	Decks	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Vales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

This vessel appears in good & efficient condition, and in my opinion, eligible to be classed A. 1.

The Amount of Fee.....£ is received by me,

Special.....

Certificate (if required)

Committee's Minute 17th April 18 66

Character assigned B. 1.

S.S. No 2. 66



© 2019

Lloyd's Register Foundation

IRON 439-0278