

REPORT of SURVEY for REPAIRS.

Rec 14/5/66

No. in Reg. Book. **No. 2478** Survey held at Glasgow Date 6th April 1866
 on the Chas. Lewis Steamer Palermo Master Dumbreck
 Tonnage 380 Built at Glasgow When built 1861
 By whom built 289 Charles Cunell & Co Owners Handyside & Henderson
 Port belonging to Glasgow Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock A. Stephen & Sons Patent Slip

Last Survey, No. 4093 Port Glasgow Classed C.A. 1.

REPAIRS The whole of the Ceiling fitted in each hold (T.S. 65) 2.65
Renewed a few rivets in Carboard Strakes on each side in Midships
Two Lengths of upper angle 1 Bay to Main Keelson under Boiler
Cement where injured repaired, Ceiling refitted and fastened; Bottom Scraped
and Coated with Red Lead, Bulwarks repaired; Boiler taken out and repaired
Bottom in way of same Scraped and all Oxidation cut & beaten off and
the plating carefully examined in way of same and found good
Keel Cemented in way of Boiler Space

Present Condition of the

Decks <u>Where Seen Good</u>	<u>Ninety</u> <u>Where Seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Treenails <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Breasthooks and Stemson <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the openings <u>do</u>	Condition, how ascertained <u>from examination</u>
Planksheers <u>do</u>	Ditto Ditto at other places <u>do</u>	Sails <u>Complete</u>
Sheerstrakes <u>Where</u> <u>do</u>	Keelsons <u>do</u>	Anchors No. of <u>3, 1 Star 2 Wedge</u>
Topsides <u>do</u> <u>do</u>	Clamps and Shells <u>do</u>	Cables <u>Complete</u>
Wales <u>do</u> <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps <u>do</u>
Plank (Bottom) and Counter <u>do</u> <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
	Copper <u>When put on</u>	

General Observations and Opinion,

As in good Condition Eligible in my opinion to remain as Classed

The Amount of Fee.....£ 1 : 0 : 0 is received by me.

Special..... 1 : 1 : 0

Certificate (if required) 7 : 0 : 0

Committee's Minute 15th May 1866

Character assigned C.A. 1

Record repair



© 2019

Lloyd's Register
Foundation
IRON439-0346