

REPORT of SURVEY for REPAIRS.

in Book. No. 5478 Survey held at London Date May 11th 18 67
 on the 8th Tamerlane Master Hughes
 Tonnage 764 Built at Greenock When built 1861
 By whom built Scott Owners J. & W. Stuart
 Port belonging to London Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock in Union & East India Docks

Last Survey, No. 5412 Port London Classed 12 A1
 REPAIRS 2.5.66.

Scraped, and painted bottom with two coats of composition paint and one of tallow.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>Rivets where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B, 1 S, 2 K</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/>	Standing & Running Rigging

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. where seen Good

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ — : — : is received by me, John Maxwell
 Special..... — : — :
 Certificate (if required) : :

Committee's Minute 14th May 18 67

Character assigned 12 A1 M.S.

AY

Say

A 1

S. S. No 1 - 116

18/5/67



© 2019

Lloyd's Register Foundation

IRON 440 - 0487