

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 20814** Survey held at Liverpool Date Aug^r 8 to 29 18 67
 on the Br^g "Eastham" Master Wiseman
 Tonnage 611 Built at Preston When built 1864 3rd
 By whom built Macfarn Owners Tennant & Co.
 Port belonging to Liverpool Destined Voyage San Francisco
 If Surveyed Afloat Yes Dry Dock Lanning graving & Tallhouse dock
 Last Survey, No. 3658 Port Iron Classed A 1 64

REPAIRS

All the Ceiling in flat of bottom & part of keelges both sides fore & aft - removed, all oxidation beaten & scraped off; the surfaces of the plating, rivetting &c found good & now coated with composition & other paint; & the Cement in flat of bottom renewed in places.

Present Condition of the

Decks	Freemasts <u>Good</u>	Windlass and Capstan <u>Good & sufficient</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>Seen from deck</u>
Planksheers	Keelsons	Sails <u>Good & sufficient</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plates	Cement <u>Good</u> When put on <u>1864</u>	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Good</u>	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Satisfactory

I am now in an efficient condition & in my opinion eligible to remain as classed, & now rated S.S. No. 1 - 1867

The Amount of Fee.....£ - : - is received by me

Special..... 2 : 2 : " 4/9/67

Certificate (if required) " : 5 : "

Committee's Minute Liverpool 6th September 1867

Character assigned A 1 3.5 Nov. 67

Class - 64 - 1867



© 2019

Lloyd's Register Foundation

1R0N441-0167

REPORT OF SURVEY FOR REPAIRS

No. 70

Surveyed by
Date
Place
Ship
Cargo
Remarks

REPAIRS

1

Particulars	Amount	Total
Repairs to hull	100.00	100.00
Repairs to deck	50.00	150.00
Repairs to rigging	25.00	175.00
Repairs to engine	75.00	250.00
Repairs to boiler	125.00	375.00
Repairs to masts	50.00	425.00
Repairs to sails	25.00	450.00
Repairs to furniture	10.00	460.00
Repairs to stores	5.00	465.00
Repairs to other	5.00	470.00
Total		470.00

Eastham
2008/14



© 2019
Lloyd's Register
Foundation