

21/9/67

5721

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 20842** Survey held at Liverpool Date 29<sup>th</sup> August to 4<sup>th</sup> Sept 1867  
on the T.L.B.9 Tybica Master Herr  
Tonnage 1203 Built at Newcastle When built 1864 - 1 mo  
By whom built 1844 Owners Bayley & Leatham  
Port belonging to London Destined Voyage Sir Cape of Good Hope  
If Surveyed Afloat or in Dry Dock Clarence Graving and Ruston Dock

Last Survey, No. 5111 Port Iron Classed GA1  
"Spar. Decked" 9.66

REPAIRS  
The ceiling from bilges to middle line in each compartment. lifted: the cement in the bottom repaired and added to -  
Bottom outside scraped and recoated -

## Present Condition of the

Decks	<u>Good</u>	Keels	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Treenails		Pumps	
Comings		Breasthooks and Stemson		Boats	
Upper Deck Beams & Fastenings		Transoms, Pointers, and Crutches		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Timbers of the Frame at the openings		Condition, how ascertained	
Planksheers	<u>Where</u>	Ditto Ditto at other places		Sails	<u>Where</u>
Sheerstrakes		Keelsons	<u>Where</u>	Anchors No. of	
Topsides		Clamps and Shelves		Cables	
Wales		Ceiling		Hawsers and Warps	
Plank (Bottom) and Counter	<u>Seen</u>	Rudder	<u>Seen</u>	Standing & Running Rigging	<u>Seen</u>
General Observations and Opinion,		Copper Cemented	When put on <u>the hull</u>		
		Caulking of Bottom, Deck, & Waterways.	<u>Good Where examined</u>		

This ship is in good and efficient condition eligible to remain as classed GA1 or GA2.  
The appraisal of the Committee is classed GA1 (SSR 67)  
The Amount of Fee.....£ 1 : - : - is received by me.

Special..... 3 : 3 : -  
\* Certificate (if required) : 5 : -  
Committee's Minute Liverpool 17<sup>th</sup> September 1867  
Character assigned B1 - (S.S. No. 67)  
Clear-64 Recd Change of Master  
© 2019 Lloyd's Register Foundation  
IRON44-0182



