

REPORT of SURVEY for REPAIRS.

5940 28867

No. in Reg. Book. **No.** 225 Survey held at London Date Decr 16th 28th 1867
 on the Iron Ship "Dolbadernfasth" Master J Morgan
 Tonnage 989 Built at Sunderland When built 1863
 By whom built _____ Owners Hughes
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Union Dry Dock & East India Dock

Last Survey, No. 5264 Port Iron. Classed A. 1
 (S.S. No. 66)

REPAIRS

now done, The bottom scraped and painted and the inside surface of the iron work where exposed painted —

Present Condition of the

Decks		Freeboards	<u>Reels</u>	Windlass and Capstan	
Waterways	<u>good</u>	Breasthooks and Stemson	<u>good</u>	Pumps	<u>good</u>
Comings		Transoms, Pointers, and Crutches		Boats	<u>four</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	<u>seen</u>
Lower Deck Beams & Fastenings	<u>where</u>	Ditto Ditto at other places	<u>where</u>	Condition, how ascertained	<u>by inquiry & inspection</u>
Planksheers	<u>painted</u>	Keelsons		Sails	
Sheerstrakes	<u>do</u>	Clamps and Shelves		Anchors	No. of <u>3 B 1 S 2 H</u> <u>good</u>
Topsides	<u>do</u>	Ceiling	<u>seen</u>	Cables	<u>and</u>
Wales	<u>do</u>	Rudder		Hawsers and Warps	<u>sufficient</u>
Plank (Bottom) and Counter	<u>Scraped and painted</u>	Cooper	<u>Paint</u> When put on <u>now</u>	Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	<u>good where seen</u>		

She is now where seen in good condition fit in my opinion to remain as classed A. 1.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 3rd January 18 68

Character assigned A 1 mas



Lloyd's Register Foundation

IRON441-0392