

5943

2887

Iron (S.S. No. 1.)

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 169 Survey held at London Date Dec^r 3rd to 23rd 1867.
 on the Iron Ship "Iron Duke" Master S. Parry
 Tonnage 1435 Built at Liverpool When built 1863 (3 mo)
 By whom built Lawrence Owners Hargrove and Co.
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Blackwall dry Dock and East India Sts

Last Survey, No. 5202 Port Iron. Classed A. 1. (11.66.)

REPAIRS Now done.

Sighted bottom, scraped from keel to gunwale; bottom paved with two coats of Oxide of Iron, and 2 of "Parry's" patent composition, the topsides with two coats of Paint.

Lifted the whole of the hatches in the Hold, from keel to the lower turn of bilges, above which, removed a shake of ceiling all fore and aft, on each side; scraped the whole of the iron work thus exposed, patched a few places in the cement, and washed the whole with a thin coating of cement.

Cleaned the whole of the iron work inside the ship, from the close ceiling up, and painted the same. Cement in good condition.

Present Condition of the

Decks	<u>good</u> <u>where</u> <u>See</u>	Transoms	<u>good</u> <u>where</u> <u>See</u>	Windlass and Capstan	<u>good</u> <u>and</u> <u>sufficient</u> <u>where</u> <u>See</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. 15. 16</u>	
Topsides		Ceiling		Cables	
Wales		Rudder <u>good</u>		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>Paint</u> When put on <u>now</u>		Standing & Running Rigging	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where See</u>				

She is now in good and efficient condition and fit in my opinion to remain Classed A. 1. and to be marked in the Register Book (S.S. No. 1. 67.)

The Amount of Fee.....£ — : — : is received by me,

Special.....2 - 2 - 0

Certificate (if required) : 5 :

Committee's Minute in January 1868

Character assigned A 1

S. S. No. 1-67

M.A.S.



© 2019

Lloyd's Register Foundation

IRON44-0395