

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 57 Survey held at LONDON Date April 16th to 23rd 1868.
 on the Iron Ship "Yamerville" Master J. Hughes
 Tonnage 764 built at Greenock When built 1861 (8 mo)
 By whom built Scott Owners J and W Stuart
 Port belonging to Greenock Destined Voyage Shang Haï
 If Surveyed Afloat or in Dry Dock Wigram & Co Dock and East India St

Last Survey, No. 5478 Port Iron. Classed A. 1. (5.64.)
 REPAIRS Now done. S.S. No. 1.66.

Lighted bottom, scraped and payed with 2 coats of lead, and one of a mixture of Tallow &c. the topsides painted.

Lifted some of the hatchets in the hold, and found the frames, floor-plates, &c. and Cement in good Condition.

Renewed the main-topgallant mast with Red pine.

Present Condition of the

Decks	<u>good</u> <u>where</u> <u>See</u>	Treebolts	<u>good</u> <u>where</u> <u>See</u>	Windlass and Capstan	<u>good</u> <u>and sufficient</u> <u>where</u> <u>See</u>
Waterways		Breasthooks and Stemson		Pumps <u>2 M. 1 F. 1 aft</u>	
Comings		Transoms, Pointers, and Crutches		Boats <u>4</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c. <u>good</u>	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>by 64</u>	
Planksheers		Keelsons		Sails <u>And enquiry</u>	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. K. 2 1/2</u>	
Topsides		Ceiling		Cables	
Wales		Rudder <u>Had good</u>		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>Paint</u> When put on <u>now</u>		Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <u>good where</u> <u>See</u>			

She is now in good and efficient condition and fit in my opinion to remain as Classed Viz. A. 1.

The Amount of Fee.....£ : : is received by me,

Special.....

Certificate (if required) : :

Committee's Minute 28th April 18 68

Character assigned A 1



© 2019

Lloyd's Register Foundation

IRON442-0151