

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 384 Survey held at London Date April to 15<sup>th</sup> May 1867  
 on the Iron Ship "Hinefred" Master William Sargent  
 Tonnage 1359 Built at Liverpool When built 1835  
 By whom built Sharples Owners Sharples  
 Port belonging to Liverpool Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Green's Lower dock and East India dock.

Last Survey, No. 4628 Port IRON Classed 9. A. 1. for 5 yrs. 3.86.

## REPAIRS

Now done:- Scraped and painted the Bottom with one coat of red-lead; two of M<sup>c</sup> Linnis brown and one of green. Painted the Topsides with oxide of Iron.

Renewed the Mizzen Mast with Oregon; Mizzen Topmast, Mizzen Topgallant-mast, Fore-topmast, Fore Topgallant Mast, the upper Fore-top-sail-yard, and the Main Topgallant Mast, with Red-pine.

The whole of the standing rigging throughout, renewed with galvanized Iron wire-rope. Dispensed with all the channel-boards, altered the form of the chain-plates and re-riveted them.

The Captain informed me that she was fumigated in the Bottom in 1862. The owner declines Triennial Survey now:- see letter, dated 29<sup>th</sup> April, attached.

Present Condition of the

Decks	Rivets.	Windlass and Capstan
Waterways	Free-nails	Pumps <u>500</u>
Comings	Breasthooks and Stems	Boats <u>400</u> } Good where seen.
Upper Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Timbers of the Frame at the openings	Condition, how ascertained <u>By inquiry &amp; observation</u>
Planksheers	Ditto Ditto at other places	Sails <u>Good</u>
Sheerstrakes	Keelsons	Anchors No. of <u>30 15 20</u>
Topsides	Clamps and Shelves	Cables <u>and</u>
Wales	Ceiling	Hawsers and Warps <u>sufficient</u>
Plank (Bottom) and Counter	Rudder	Standing & Running Rigging <u>new</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

She is now in good and efficient condition, and fit, in our opinion, to remain as classed: A. 1.

The Amount of Fee.....£ — : — : is received by me,

Special..... 1 : 1 :

Certificate (if required) : 5 :

Committee's Minute 1<sup>st</sup> May 18 68

Character assigned Cont 5 A 1 MAS



© 2019

Lloyd's Register Foundation

IRON 442-0166