

6274

REPORT of SURVEY for REPAIRS.

Rev 5/6/68

No. in
Reg. Book.
373

No. 1554 Survey held at Swansea Date 28 May to 4 June 1868
 on the Iron S.S. John Brodew Master Philip Dolbel
 Tonnage 548 Built at Newcastle When built 1866
 By whom built Mitchell Owners A. Brodew
 Port belonging to Swansea Destined Voyage France
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 5839 Port Iron Classed A 1
 10.67

REPAIRS in consequence of running against a Pier in France
 on Port Bow one plate renewed. old one broken.
 Four Angle Irons repaired. old ones broken.
 on Starboard Side abreast Foremast a plate badly bent taken
 out, straightened, and replaced.
 One Angle Iron repaired old one broken.

Present Condition of the

Decks	Good	Treenails	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	Condition, how ascertained	off Deck
Planksheers	"	Keelsons	Sails	"
Sheerstrakes	"	Clamps and Shelves	Anchors No. of	3 B. 1 S. 2 K.
Topsides	"	Ceiling	Cables	"
Wales	"	Rudder	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	Standing & Running Rigging	"

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where examined

This ship has been surveyed by me, is now in good condition and
 in my opinion eligible to be continued as classed A 1

The Amount of Fee.....£ 1 : : : is received by me,

May 1868

Special..... 1 : 1 :
 Telegrams..... 4 :
 Certificate (if required) : 4 :


W. Johnson

Committee's Minute 5th June 18 68

Character assigned

A 1

record damages repairs



© 2019

Lloyd's Register
Foundation

IRON 442-0243