

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 158 Survey held at London Date June 5th 18 68
 on the "Knight Barant" Master D. Taylor
 Tonnage 1312 built at Hull When built 1858
 By whom built Owners Farlyfe
 Port belonging to Birkenhead Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock in Victoria, Thames Iron Works & East India Docks

Last Survey, No. 5564 Port Iron Classed A1
S.S. No 3-64 6.67

REPAIRS

Lifted timber hatches and ceiling at bilges equal to a stroke on each side for examination of cement, frames, floor plates &c all of which were found to be in good condition, the cement adhering in a very satisfactory manner. Scraped and painted bottom with two coats of composition paint. — Renewed windlass of Leak.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>Rivets where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " " "</u>	Breasthooks and Stemson <u>" " " "</u>	Pumps <u>" " " "</u>
Comings <u>" " " "</u>	Transoms, Pointers, and Crutches <u>" " " "</u>	Boats <u>" " " "</u>
Upper Deck Beams & Fastenings <u>" " " "</u>	Timbers of the Frame at the openings <u>" " " "</u>	Masts, Yards, &c. <u>" " " "</u>
Lower Deck Beams & Fastenings <u>" " " "</u>	Ditto Ditto at other places <u>" " " "</u>	Condition, how ascertained <u>from enquiry was seen from deck</u>
Planksheers <u>" " " "</u>	Keelsons <u>" " " "</u>	Sails <u>" " " "</u>
Sheerstrakes <u>" " " "</u>	Clamps and Shelves <u>" " " "</u>	Anchors No. of <u>2 B. 1 S. 2 K.</u>
Topsides <u>" " " "</u>	Ceiling <u>" " " "</u>	Cables <u>" " " "</u>
Wales <u>" " " "</u>	Rudder <u>" " " "</u>	Hawsers and Warps <u>" " " "</u>
Plank (Bottom) and Counter <u>" " " "</u>	Copper <u>✓</u> When put on <u>✓</u>	Standing & Running Rigging <u>" " " "</u>
General Observations and Opinion, <u>Caulking of Bottom, Deck, & Waterways. where seen Good</u>		

Is now in good and efficient condition and in my opinion eligible to remain as classed, and be marked "S.S. No 1. 68"

The Amount of Fee.....£ — : — : is received by me, John Maxwell

Special..... 2 : 2 : 0 APD

Certificate (if required) : :

Committee's Minute 16th June 18 68

Character assigned A1

S.S. No 1 = 68 MS



© 2019

Lloyd's Register Foundation

IRON442-0254