

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 575 No. 3039 Survey held at Glasgow Date Oct 18 62 18 69
 on the Iron Ship "City of Benares" Master J. Smith
 Tonnage 1187 built at Glasgow When built 1865
 By whom built Barclay Owners Smith & Sons
 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Meas^r Inglis Patent Slip

Last Survey, No. 4266 Port Iron Classed A. 1.
 8.65

REPAIRS

Now done,

The bottom scraped and painted; the timbers and a strake of ceiling, from the after bulkhead forward, on both sides, lifted; the cement found to be adhering satisfactorily to the iron, and the iron work in good condition, the vessel has been recently painted inside and is in good and efficient condition - At the flat of the after hold is covered with outward cargo, the Owners intend to submit her on her return for the completion of the No 1 Survey -

Three rough tree stanchions and one shift of covering board on the Port side amidships, renewed with Teak, and three seams of deck next caulked -

Present Condition of the

Decks	} good	Trunnions	} good	Windlass and Capstan	} good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} firm	Timbers of the Frame at the openings	} where	Masts, Yards, &c.	} efficient
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes	} where	Clamps and Shelves	} good	Anchors No. of 3/13 15 24	} sufficient
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter	seen	Copper Cement When put on 1865	Standing & Running Rigging		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

No 1 Survey has now been complied with, with the exception of the flat of after hold, and the vessel found to be in good and efficient condition, and fit in my opinion to remain as classed

The Amount of Fee.....£ " : " : " is received by me,

Special.....£ 3 : 3 : "

Certificate (if required) " : " : "

Committee's Minute 9th November 1869

Inspector assigned

Hornish
 © 2019
 Lloyd's Register
 Foundation