

# REPORT of SURVEY for REPAIRS.

No. 2277 Survey held at Birkenhead Date, first Survey 20<sup>th</sup> Sept Last Survey 11<sup>th</sup> Oct 1869  
 on the Vicar Br "Ribbleton" Master Bewley M. Lopez B. S. No. 13 \*  
 Tonnage 398 built at Preston When built 1865-9 mo  
 By whom built Mackern Owners Sellock & Manuel Lopez \*  
 Port belonging to Liverpool Destined Voyage Algeria (Spain) \*  
 If Surveyed Afloat or in Dry Dock Cloar's dry dock \* Vide her Letter 29/11/69  
 Last Survey, No. 6364 Port Iron Classed A 1 Fee Paid 68

## REPAIRS, &c.

Through damage  
 one sheerstrake plate and one Bulwark plate and also two short  
 pieces of Angle Iron to Stringer or Deck Beams - one frame scarped  
 part also Main Rail, all on the Starboard side, one deck plank  
 and one new boat

## Periodical Survey

Ceiling (in hatches) equal to three strakes all fore and aft on both  
 sides lifted, the cement coating, floors &c examined and found  
 in good condition - outside cleared and painted

## Present Condition of the

Decks	} Good	Timber	} Good	Windlass and Capstan	} Good	
Waterways		Breasthooks and Stemson		Pumps		
Comings		Transoms, Pointers, and Crutches		Boats		
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.		
Lower Deck Beams & Fastenings	} where	Ditto Ditto at other places	} where	Condition, how ascertained	} and	
Planksheers		Keelsons		Sails		
Sheerstrakes		Clamps and Shells		Anchors No. of		
Topsides		Ceiling		Cables		
Wales	} Seen	Rudder	} where	Hawsers and Warps	} Seen	
Plank (Bottom) and Counter		Copper		When put on		Standing & Running Rigging
Engine Room Skylights		Caulking of		1865		Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways		Good		Hatches
General Observations and Opinion,		Scuppers	Good			

She is now in good condition and in my  
 opinion may continue as classed and marked S S No 1. / 69

The Amount of Entry Fee.....£ 1 : " : " is received by me.


Special..... 2 : 2 : - 4/11/69

Certificate (if required) " : 5 : "

Committee's Minute Liverpool 9<sup>th</sup> November 1869

Character assigned A 1 - Accord Damage Repair S. S. No. 1. / 69

Special or Damage S. S. 3. 19/10/69



© 2019

Lloyd's Register  
Foundation

IRON 445-0104

REPORT OF SURVEY FOR REPAIRS.

"Pittsboro"  
-22077-



© 2019

Lloyd's Register  
Foundation