

7854

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. No. 2226 Survey held at Liverpool Date Nov. 13/4/70
on the Ship Hannibal Master J. H. Hill
Tonnage 1198 Built at Glasgow When built 1862
By whom built Smith Owners G. Dixon
Port belonging to Liverpool Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Canoe Graving Dock and afloat.

Last Survey, No. 3426 Port Liverpool Classed 12 A1
(See annexed reports)

REPAIRS

The timbers and Ceiling / in Kitchens / lifted all fore and aft on both sides, the Cement coating found to be in good condition and adhering satisfactorily to the iron. The plating, rivets &c. were all in good condition.

Bottom scraped clean and coated with H. S. Iron's Composition inside with Paint. Caulked around Wood Stanchions.

Present Condition of the

Decks	Timber	Windlass and Capstan	Good
Waterways	Breasthooks and Stemson	Pumps	Good
Comings	Transoms, Pointers, and Crutches	Boats	Good
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained	Seen from the Deck
Plank sheers	Keelsons	Sails	Good
Sheerstrakes	Clamps and Shelves	Anchors No. of	3 Good
Topsides	Ceiling	Cables	and
Wales	Rudder	Hawsers and Warps	Sufficient
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging	Good
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.		Good

Is now in good and efficient condition, and in my opinion eligible to remain as classed 12 A1.

The Surveyor wishes the Character changed to A1. Should the Committee be pleased to sanction the same.

The Amount of Fee.....£ : : is received by me.

Special..... 3 : 3 : -

Certificate (if required) : off : -

Committee's Minute Liverpool 12 April, 1870

Character assigned A1