

REPORT of SURVEY for REPAIRS.

Rev 13/5/70

No. in Reg. Book. **No. 3112** Survey held at Bristol Date 5th May 1870
 59 on the SS "Warrior" Master H. Lant
 Tonnage 490 built at Stockton When built 1858
 By whom built _____ Owners Tennant & Co
 Port belonging to Leeds Destined Voyage Bristol to S. America
 If Surveyed Afloat or in Dry Dock Dry Dock
 Last Survey, No. 6558 Port Irons Leeds Classed A1. S.S. 4-2-68
 REPAIRS g. 68

Outside surface of plating scraped, and Coated: The Bottom with Lucie Paint & Tallow upon it, the upper works with ordinary Paint.

Examined inside as far as Ballast permitted and found all good.

Present Condition of the

Decks	<u>Good</u>	Timbers	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Pumps	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	<u>Three</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the openings	<u>do</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto Ditto at other places	<u>do</u>	Condition, how ascertained	<u>from deck</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>	Sails	<u>well found</u>
Sheerstrakes	<u>plating</u>	Clamps and Shelves	<u>do</u>	Anchors	No. of <u>3 B. 1. S. & R. 8</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>	Cables	<u>complete</u>
Wales	<u>do</u>	Rudder	<u>do</u>	Hawsers and Warps	<u>sufficient</u>
Plank (Bottom) and Counter	<u>do</u>	Copper	<u>Bottom Coated</u>	Standing & Running Rigging	<u>good</u>
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		<u>good</u>	

This Vessel being in good Condition, I am of opinion she may remain as classed.

The Amount of Fee.....£ : : is received by me,

Special..... / : / :

x Certificate (if required) : 5 :

Committee's Minute 13th May 1870

Character assigned A1



© 2019

Lloyd's Register Foundation

IRON446-0192

Capt. Lant. SS "Warrior". By H. Lant & J. Jones. 3 New Lane. Office. Wharf. W. 1870.