

ANNUAL SURVEYS.

No. 22456 Survey held at Liverpool Date 10 August 7 Sept 18 70
 on the BARQUE "BROUGHTON" Master Lundberg
 Tonnage 580 Built at Belfast When built 1868 1. mo
 By whom built Harland Owners Amey Coy.
 Port belonging to Liverpool Destined Voyage Lima
 If Surveyed Afloat or in Dry Dock Canning Dry Dock and afloat

Last Survey, No. 6079 Port of Irish Classed * A. S. 3.68.

The present Condition of the

Decks	Greenails <u>Rocks</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1868</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Bottom Scraped and painted. Is now in good condition.
and in my opinion is fit to remain as classed.

Committee's Minute Liverpool 13th Sept 1870

Character assigned * A

M. L.

Certificate (if required)

No. 60 Survey held at Liverpool Date 22 August 10 Sept 18 70
 on the SHIP "CAMBRIAN" Master Smith
 Tonnage 620 Built at Liverpool When built 1867 8. mo
 By whom built Broadley Owners J. Walmsley
 Port belonging to Liverpool Destined Voyage South America
 If Surveyed Afloat or in Dry Dock Canning Dry Dock and afloat

Last Survey, No. 6499 Port of Irish Classed * A. S. 9.68.

The present Condition of the

Decks	Greenails <u>Rocks</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1867</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Bottom Scraped and painted. Is now in good condition
and in my opinion is fit to remain as classed.

Committee's Minute Liverpool 13th Sept 1870

Character assigned * A

M. L.

Certificate (if required).

IRON 447-0064

"Broughton"
22456
"Cambrian"



© 2019

Lloyd's Register
Foundation