

REPORT of SURVEY for REPAIRS.

8617

Rec 3/11/70

No. in Reg. Book. 105 No. 3224 Survey held at Glasgow Date, first Survey 24th Oct Last Survey 28th Oct 1870
 on the S. S. 'Kinsale' Master Mc Kellar
 Tonnage 499 built at Renfrew When built 1865
 By whom built Henderson & Co Owners Glasgow, Corn & Waterford S. Co
 Port belonging to Glasgow Destined Voyage Coaster
 If Surveyed Afloat or in Dry Dock on Patent Ship
 Last Survey, No. 7914 Port Iron Classed B.1
 REPAIRS, &c. S.S. No 1. / 68. 4.70

now done. —

Seven bottom plates on St^a side, and two on Port side cut out, and renewed, nine butt straps on St^a side, and three on Port side cut out & renewed, 220 ft of edges of plating on St^a side periveted, with 120 feet on Port side. —
 500 feet of edges of plating on St^a side, and 200 feet on port side recaulked, 30 Butt Straps on St^a side, and 23 on port side recaulked, asphalt on inside of plating repaired with cement, 100 feet of ceiling renewed with A. Elm. Main deck caulked, machinery repaired, and bottom cleaned, and painted, —

Present Condition of the

Decks	Greenails	Rivets, part renewed	Windlass and Capstan	Good
Waterways	Breasthooks and Stemson		Pumps	Do
Comings	Transoms, Pointers, and Crutches		Boats	Do
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings		Masts, Yards, &c.	Do
Lower Deck Beams & Fastenings	Ditto Ditto at other places		Condition, how ascertained	See from deck
Planksheers	Keelsons		Sails	
Sheerstrakes	Clamps and Shelves		Anchors No. of	Good
Topsides	Ceiling		Cables	and
Wales	Rudder		Hawsers and Warps	Sufficient
Plank (Bottom) and Counter	Copper Alp & Cem. When put on	Good part an	Standing & Running Rigging	Good
Engine Room Skylights	Caulking of			
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Good		
General Observations and Opinion,	Scuppers	Good		
	Cargo and Main Hatchways	Good		
	Hatches	Good		

This Vessel is now in good, and efficient condition and in my opinion eligible to remain as classed. —

The Amount of Entry Fee.....£ / : : ' is received by me,

Special.....£ : : ' : :

Certificate (if required) : : : :

Committee's Minute 4th November 1870

Character assigned B.1

W.A. record repair



© 2019

Lloyd's Register Foundation

IRON 447-0223