

REPORT of SURVEY for REPAIRS.

8573

No. in Reg. Book. 398 No. 1267 Survey held at London Date, first Survey 23rd Nov^r Last Survey Dec^r 10th 1870
 on the Iron Ship British Consul Master Charles Raymond
 Tonnage 1267 built at Liverpool When built 1866 8th mth
 By whom built Royden Owners British Ship Owners Comp^y
 Port belonging to Liverpool Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Greens upper dock & East India Docks.
 Last Survey, No. 6423 Port Iron Classed *A.1.
8.68

REPAIRS, &c.

Lifted the timbers, and hatches each side the middle line, more than equal to a strake fore and aft. Cleaned her outside and inside. examined ribs, rivets, floors, Keelsons. Keel. - found the Cement adhering satisfactorily. - Made good the Rudder pintles, and braces by rebushing and refitting. - Recoated her outside, and painted her inside repaired the Cement where necessary. -

Present Condition of the

Decks	good	Freemasts	Rivets where seen good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	from the deck "
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of 3 & 1 S. 2 K	"
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder efficient	"	Hawsers and Warps	"
Planks (Bottom) and Counter	"	Copper When put on	"	Standing & Running Rigging	"
Engine Room Skylights	"	Caulking of	good		
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	good		
Scuppers	good	Cargo and Main Hatchways	good	Hatches	good

General Observations and Opinion,

She is now in good condition, and the Survey Rule No. 1. having been complied with - I am of opinion she is entitled to remain as classed *A.1. and to be marked in the Regⁿ S.S. No 1/50

The Amount of Entry Fee.....£ — : — : is received by me,

Special..... 2 : 2 : } 28/12/70

Certificate (if required) : 5 :

Committee's Minute 30th December 1870

Character assigned *A.1.

Samuel Sessions



© 2019

Lloyd's Register Foundation

IRON 447-0378

British Consul

REPORT OF SURVEY FOR REPAIRS.



© 2019

Lloyd's Register
Foundation