

8733

37597

REPORT of SURVEY for REPAIRS.

No. in Book. 84 No. 595 Survey held at London Date, first Survey 4<sup>th</sup> April Last Survey April 9<sup>th</sup> 1870.  
on the Iron Screw Steamer May Queen Master Hansman 2<sup>d</sup> Harrison  
Tonnage 595 built at London When built 1864  
By whom built Langley Owners Gen<sup>l</sup>. Iron Screw Col<sup>d</sup> Compy  
Port belonging to London Destined Voyage Coasting  
If Surveyed Afloat or in Dry Dock Upper Globe Dry dock  
st Survey, No. 7175 Port Iron. Classed C. A. 1. t.s. in 67.  
PAIRS, &c. Copied

Lifted the Boilers. Cleared out the coal bunniers.  
Examined the Cement in wake of the foregoings, and found  
it adhering satisfactorily. and all in good condition. inside  
and outside (as far as seen) - Ribs, Rivets, floors and plating.  
Ulcated the outside with black varnish. - Deck renewed  
in wake of boiler hatch, and caulked.

Present Condition of the

cks	good	Treenails	Rivets	good	Windlass and Capstan	in good order
terways	"	Breasthooks and Stemson		"	Pumps	"
nings	"	Transoms, Pointers, and Crutches		"	Boats	"
per Deck Beams & Fastenings	"	Timbers of the Frame at the openings		"	Masts, Yards, &c.	"
wer Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Condition, how ascertained	from the Dk
anksheers	"	Keelsons		"	Sails	"
eerstrakes	"	Clamps and Shelves		"	Anchors No. of 3	"
psides	"	Ceiling		"	Cables	"
ales	"	Rudder	efficiently	"	Hawsers and Warps	"
ank (Bottom) and Counter	"	Copper	<del>XXXXXX</del> When put on	"	Standing & Running Rigging	"
ngine Room Skylights	good	Caulking of	good			
Coal Bunker, Openings, Lids, &c.	good	Bottom, Deck, & Waterways				
Scuppers	good					
Cargo and Main Hatchways	good					
Hatches	good					

General Observations and Opinion,

She is as far as seen in good condition  
and is in my opinion entitled to remain as classed C. A. 1.

Samuel Presons

The Amount of Entry Fee.....£ : : is received by me,  
Special..... / : / :  
Certificate (if required) : : }

Committee's Minute 7<sup>th</sup> February 1871

Character assigned





Mary Green

REPORT OF SURVEY OF REPAIRS



© 2019

Lloyd's Register  
Foundation