

Iron. 8886  
Change of Owners.

37504

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 5 No. 7380 Survey held at London Date, first Survey 7<sup>th</sup> March Last Survey 23<sup>rd</sup> March 1871  
on the Ship "Haddington" Master Sargent  
Tonnage 1459 built at Liverpool When built 1846  
By whom built — Owners L. Young & Co.  
Port belonging to London Destined Voyage Bombay  
If Surveyed Afloat or in Dry Dock Regent Dry Dock.  
Last Survey, No. 7380 Port London Classed \*A1  
(S. S. No 1-68.)  
9.69.

Outside cleaned and painted, and bottom calowed.  
Rudder pintles bushed.

## Present Condition of the

Decks	Freeboards	Pivots	Windlass and Capstan
Waterways	Breasthooks and Stems		Pumps
Comings	Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Good	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Good	Condition, how ascertained
Planksheers	Keelsons	where	Sails
Sheerstrakes	Clamps and Shells	seen.	Anchors No. of
Topsides	Ceiling		Cables
Wales	Rudder		Hawsers and Warps
Plank (Bottom) and Counter	Copper Asps. When put on	—	Standing & Running Rigging
Engine Room Skylights	Caulking of		
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Good where examd.	Cargo and Main Hatchways
Scuppers		Good	Hatches

General Observations and Opinion,

Is now in good and efficient condition, and fit  
in my opinion to remain classed \*A1.

J. H. Eastlake,


The Amount of Entry Fee.....£ 1 : — : + is received by me,

Special..... : — : +

Certificate (if required) : 5 : +

Committee's Minute 31<sup>st</sup> March 1871

Character assigned A



© 2019

Lloyd's Register  
Foundation

IRON/448-0239