

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *4456* No. *1* Survey held at *London* Date, first Survey *14th Feb^r* Last Survey *1 March* 18*71*
 on the *Sew Sr^l Love Bird* Master *C. Leitz*
 Tonnage *563* built at *Hull* When built *1865*
 By whom built *1448* *Humber J. W.* Owners *J. Rodenacker*
 Port belonging to *Danzig* Destined Voyage *—*
 If Surveyed Afloat or in Dry Dock *Seen in Millwall New Dry Dock.*
 Last Survey, No. *6686* Port *Iron.* Classed **A1.*
11, 68.

REPAIRS, &c.

This vessel being over due for the No 1 Special Survey, left a notice card with the Captain a copy of which is attached, at the same time explaining to him the nature of the Survey. Upon calling afterwards the Captain informed us the owner declined to submit the vessel to the Survey.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
	Caulking of	
Engine Room Skylights	Bottom, Deck, & Waterways	
Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways
		Hatches

General Observations and Opinion,

Under the circumstances above set forth we beg to submit the case for the consideration of the Committee.
J. H. Eastlake,

The Amount of Entry Fee.....£ — is received by me,

Special.....

Certificate (if required)

Committee's Minute *3rd March* 18*71*

Character assigned