

REPORT of SURVEY for REPAIRS.

10192

Rec 6/6/72

No. in Reg. Book. No. 11920 Survey held at N. Shields Date, first Survey and Last Survey 9 May 1872
 on the "S.S. Holmeside" Master N. Dryden
 Tonnage 496 built at N. Shields When built 1841 - 4 mo
 By whom built Readhead & Co. Owners Stanison & Co.
 Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Smiths dry dock.

Last Survey, No. 9533 Port London Classed 90 A 1

REPAIRS, &c. done on account of grounding & collision :- a few ribs removed in hull, several batts recaulked at hizes, the stanchions and bulwarks on S^d side of quarter deck removed, and the deck partly re-caulked.
The bottom has now been scraped and painted.

Present Condition of the

Decks <u>good where seen</u>	Rivets <u>good where seen</u>	Windlass and Capstan <u>good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto Ditto at other places <u>do</u>	Condition, how ascertained <u>by inspection</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Sails <u>efficient</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>do</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Wales <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Plank (Bottom) and Counter <u>do</u>	Copper <u>When put on</u>	Standing & Running Rigging <u>do</u>
Engine Room Skylights <u>Secure</u>	Caulking of <u>good where seen</u>	
Coal Bunker, Openings, Lids, &c. <u>Secure</u>	Bottom, Deck, & Waterways <u>seen</u>	
Scuppers <u>Secure</u>		
Cargo and Main Hatchways <u>Secure</u>		
Hatches <u>good</u>		

General Observations and Opinion, This vessel appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

The Amount of Entry Fee.....£ _____ is received by me, H. Read.
 Special.....3
 Certificate (if required) _____

Committee's Minute 7 June 1872
 Character assigned 90 A 1

