

REPORT of SURVEY for REPAIRS.

11300

Survey held at Hull Date, first Survey 13th Feb Last Survey 29th April 1873
 Name of Ship SS. M. Neptune Master John Parrott
 built at Newcastle When built 1870 - 5 mo
 built Hornby Owners J F Bell
 going to S Shields Destined Voyage Newcastle Coast
 layed Afloat or in Dry Dock In Gibsons dry dock & afloat in Stambol St
 No. 8198 Port Iron Classed B 1
8.70

Now done - Limbers and ceiling lifted as required
 and the plating inside above close ceiling and
 outside from Keel to Gunwale scraped & painted
 Sir Butts at the port bilge overhauled and
 partly rivetted. Propeller broken and
 renewed Deck Caulked

Present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Windlass and Capstan	<u>Which good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>Good</u>	Pumps	<u>good</u>
Fastenings	<u>do</u>	Transoms, Pointers, and Crutches	<u>Good</u>	Boats	<u>26 No do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the openings	<u>Good</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto Ditto at other places	<u>Good</u>	Condition, how ascertained	<u>Inspection</u>
Planksheers	<u>Good</u>	Keelsons	<u>Good</u>	Sails	<u>good sufficient</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>Good</u>	Anchor	<u>No. of 2 B 18 r 11 kg</u>
Topsides	<u>do</u>	Ceiling	<u>Good</u>	Cables	<u>good</u>
Wales	<u>do</u>	Rudder	<u>Good</u>	Hawsers and Warps	<u>good</u>
Plank (Bottom) and Counter	<u>do</u>	Copper	<u>Good</u>	Standing & Running Rigging	<u>good</u>
Engine Room Skylights	<u>good</u>	When put on	<u>Good</u>	Cargo and Main Hatchways	<u>good</u>
Coal Bunker, Openings, Lids, &c.	<u>good</u>	Caulking of	<u>Good</u>	Hatches	<u>good</u>
General Observations and Opinion,	<u>good</u>	Bottom, Deck, & Waterways	<u>good</u>		

This vessel having complied with the rules
 Survey No 1 is now in good condition and eligible
 in my opinion to remain as classed B 1 and
 marked S.S. No 1-73

The Amount of Entry Fee.....£ 10 - is received by me,

Special..... 3 : 3 -

Certificate (if required) - : - : -

Committee's Minute 6th May 1873

Character assigned B 1

S.S. No 1-73 Com.



© 2019

Lloyd's Register
Foundation

IRON 453 042