

12083

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 424 No. 3400 Survey held at Bristol Date, first Survey 23 Nov Last Survey 28 Nov 1873  
 on the "Hutton Chayton" Master Jack  
 Tonnage 580 built at Newcastle When built 1855  
 By whom built \_\_\_\_\_ Owners Genl Iron Screw Collier Comp  
 Port belonging to London Destined Voyage France  
 If Surveyed Afloat or in Dry Dock dry dock

Last Survey, No. 10857 Port London Classed A. S. S. No 3. 70.  
12.7.73.

## REPAIRS, &c.

Rudder repaired. Bottom scraped and recoated. Several rivets renewed.

The survey No 1 being now due upon this vessel notice of the same was sent by me to Owners, and S. P. No 2 recommended. Answered is Owners reply declining the survey.

### Present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto Ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchor No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	Standing & Running Rigging _____
Engine Room Skylights _____	Caulking of _____	
Coal Bunker, Openings, Lids, &c. _____	Bottom, Deck, & Waterways _____	
Scuppers _____	Cargo and Main Hatchways _____	Hatches _____

### General Observations and Opinion,

I beg to leave the case of this vessel in the hands of the Committee

The Amount of Entry Fee.....£ : : is received by me,

*Dec 11/73*

Special.....

Certificate (if required) : :  
 Damage fees 3-3  
 Committee's Minute 9<sup>th</sup> December 1873

*Thomas Congdon*

Character assigned A 1

*J. W. M.* write owners letter 10.12.73



© 2019 Lloyd's Register Foundation