

REPORT of SURVEY for REPAIRS.

Rev 2/3/74

No. in Reg. Book. 71 No. 12367 Survey held at Newcastle Date, first Survey 22nd and Last Survey 27th January 1874.
 on the S.S.S. "James Southern" Master G. Mc Intyre
 Tonnage 501 built at North Shields When built 1865 - 5th mo.
 By whom built Smith Owners Dixon & Co
 Port belonging to London Destined Voyage Rochester
 If Surveyed Afloat or in Dry Dock Wallsend Patent Slip

Last Survey, No. 10204 Port from Newcastle S.S. Shl. No 2-72. Classed 90A 3/72.

REPAIRS, &c. On account of having grounded on the mussel scalp. About thirty rivets in the bottom renewed, a few butts and keel scarp & caulked, and the bottom recoated.

Present Condition of the

Decks	<u>Good.</u>	Ironails	<u>Good.</u>	Windlass and Capstan	<u>Good.</u>
Waterways	<u>do.</u>	Rivets	<u>do.</u>	Pumps	<u>do.</u>
Comings	<u>do.</u>	Breasthooks and Stemson	<u>do.</u>	Boats	<u>3 in No. do.</u>
Upper Deck Beams & Fastenings	<u>do.</u>	Transoms, Pointers, and Crutches	<u>do.</u>	Masts, Yards, &c.	<u>do.</u>
Lower Deck Beams & Fastenings	<u>do.</u>	Timbers of the Frame at the openings	<u>do.</u>	Condition, how ascertained	<u>From the deck and by inquiry</u>
Planksheers	<u>do.</u>	Ditto <u>framing</u> at other places	<u>do.</u>	Sails	<u>Sufficient</u>
Sheerstrakes	<u>do.</u>	Keelsons	<u>do.</u>	Anchors	<u>No. of 3 B. 1 S. 2 K.</u>
Topsides	<u>do.</u>	Clamps and Shells	<u>do.</u>	Cables	<u>Complete not ranged</u>
Wales	<u>do.</u>	Ceiling	<u>do.</u>	Hawsers and Warps	<u>Sufficient</u>
Plank (Bottom) and Counter	<u>do.</u>	Rudder	<u>do.</u>	Standing & Running Rigging	<u>Good.</u>
Engine Room Skylights	<u>Good.</u>	Copper	<u>When put on</u>		
Coal Bunker, Openings, Lids, &c.	<u>Good.</u>	Caulking of			
Scuppers	<u>Good.</u>	Bottom, Deck, & Waterways	<u>Good where tried</u>		
Cargo and Main Hatchways	<u>Secure</u>				
Hatches	<u>Good.</u>				

General Observations and Opinion,

This vessel is in good condition, and eligible in my opinion to remain as classed.

J. H. Cooke.

The Amount of Entry Fee.....£ - : - : is received by me,

Damage Survey Special..... 2 : 2 : -

Feb 1874 Certificate (if required) - : - : -

Committee's Minute 3rd March 1874

Character assigned 90A

J. H. Cooke.



© 2019

Lloyd's Register Foundation

IRON 456-0289