

REPORT of SURVEY for REPAIRS.

No. in Reg. Book 38 No. 12477 Survey held at London Date, first Survey 14th February Last Survey 16th February 1874.
 on the Iron S.S. Windsor Castle Master Howdon
 Tonnage 2572 built at Glasgow When built 1873 (4th Mo.)
 By whom built Napier Owners Donald Gunn & Co.
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Thames Dry Dock and South West India Dock.

Last Survey, No. 12117 Port of London Iron. Classed 100 A.I. 11/73.

REPAIRS, &c.

The Bottom sighted, scraped and painted. Caulked a few of the Butts.

Two shakes of filting were lifted on each side of the after hold, and the Cement carefully examined, and found in good condition and adhering satisfactorily to the Iron work. This was done to assist of owners taking in some permanent knowledge.

Present Condition of the

Decks	} <u>Good.</u>	<u>Keels</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good</u>
Waterways		<u>Transoms, Painters, and Gritches</u>		Pumps	
Comings	} <u>Fair.</u>	<u>Timbers of the Frame at the openings</u>	} <u>Good</u>	Boats	} <u>Good</u>
Upper Deck Beams & Fastenings		<u>Ditto Ditto at other places</u>		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>Good.</u>	<u>Keelsons</u>	} <u>and</u>	Condition, how ascertained	} <u>sufficient</u>
Planksheers		<u>Clamps and Shelves</u>		Sails	
Sheerstrakes	} <u>Good.</u>	<u>Ceiling</u>	} <u>Good</u>	Anchors No. of	} <u>Good</u>
Topsides		<u>Rudder</u>		Cables	
Wales	} <u>Good.</u>	<u>Copper Paint</u> When put on <u>Now.</u>	} <u>Good</u>	Hawsers and Warps	} <u>Good</u>
Plank (Bottom) and Counter		<u>Caulking of</u>		Standing & Running Rigging	
Engine Room Skylights	<u>Efficient</u>	<u>Bottom, Deck, & Waterways</u> <u>Good.</u>	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
General Observations and Opinion,		<u>Coal Bunker, Openings, Lids, &c.</u> <u>Good</u>	<u>Good</u>	<u>Good</u>	<u>Good</u>

She is in good and efficient condition, and fit, in our opinion, to remain Classed 100 A.I.

The Amount of Entry Fee.....£..... received by me,

Special..... 1 u 1 u 0

Certificate (if required) : : :

Committee's Minute 31st March 18 74

Character assigned 100 A

Williamson
 Mr. Dawson the Surveyor
 Tinsel in Dry Dock the
 Lines of Hull