

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 12440** Survey held at Newcastle Date, first Survey 30 March Last Survey 15th April 1874
 on the S. S. "Hilda" Master J. Shotton
 Tonnage 650 built at P. Glasgow When built 1865
 By whom built Reid Owners Itteron Mining Co. Limited
 Port belonging to London Destined Voyage Baltic
 If Surveyed Afloat or in Dry Dock WallSEND Slip

Last Survey, No. xxxxx 11300 Port Newcastle ~~From~~ Classed B.1

REPAIRS, &c. now done for Damage.

4.73.
SS No. 2-69

Renewed part of Stem, also on Port side two Garboard and one bottom plate, and on Star^a side one garboard plate, Steel and Stem rivets for about 30 feet in length, renewed, Cement forward renewed, plates on the Rudder periveted, Rudder repaired, Bottom cleaned and painted.

Present Condition of the

Decks	<u>Good</u>	Tree-nails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson		<u>do</u>	Pumps	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches		<u>do</u>	Boats	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the openings		<u>do</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto Ditto at other places		<u>do</u>	Condition, how ascertained	<u>Seen from deck & enquiry</u>
Planksheers	<u>do</u>	Keelsons		<u>do</u>	Sails	<u>Good</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves		<u>do</u>	Anchors No. of	<u>Good & sufficient</u>
Topsides	<u>do</u>	Ceiling		<u>do</u>	Cables	<u>do</u>
Wales	<u>do</u>	Rudder		<u>do</u>	Hawsers and Warps	<u>do</u>
Plank (Bottom) and Counter	<u>do</u>	Copper <u>Cem</u> When put on <u>1867</u>			Standing & Running Rigging	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Caulking of			Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Bottom, Deck, & Waterways	<u>Good</u>		Hatches	<u>Good</u>
General Observations and Opinion,		Scuppers	<u>Good</u>			

This vessel is now in Good, and efficient condition, eligible in my opinion to remain as Classed.

The Amount of Entry Fee.....£ 2 : : is received by me,

Special.....

Certificate (if required)

Committee's Minute 1st May 1874

Character assigned



© 2019

Lloyd's Register
Foundation