

12850

# REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. 442 No. 3049 Survey held at Newport Date, first Survey 1 June 1874 Last Survey 1 June 1874  
on the Hon<sup>ble</sup> Britomart Master Torrill  
Tonnage 000 built at Pt Glasgow When built 1866 Home  
By whom built Pridd Owners Boyring  
Port belonging to Liverpool Destined Voyage India  
If Surveyed Afloat in Dry Dock Newport, Dry Dock  
Last Survey, No. 8802 Port Brown Classed Years assigned. \* A 1 Character in Register Book. S.S. Nov. 1/71

## REPAIRS, OR EXAMINATION AS PER RULE

Placed on Blocks in Dry Dock. Bottom cleaned & coated with Zinc Paint, & Tallow.  
Foretopmast renewed with Pitch Pine

### Present Condition of the

Decks	<u>Good</u> <u>where</u> <u>lean</u>	Treenails <u>Pivots</u>	<u>Good</u> <u>where</u> <u>lean</u> <u>Good</u> <u>lean</u> <u>Good</u>	Windlass and Capstan	<u>Good</u> <u>and</u> <u>Sufft</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>Paint</u> When put on <u>lean</u>		Standing & Running Rigging	
Engine Room Skylights	Caulking of <u>Good</u>	Cargo and Main Hatchways			
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Hatches			
Scuppers					

General Observations, Opinion as to Class, &c.

Vessel appears to be in good and efficient condition, eligible to remain as classed \* A 1.

The Amount of Entry Fee ... £ 1 : 1 : 0 received by me, Henry J. Torrill  
Special ... £ 5 : 0 : 0  
Certificate (if required) ... £ 5 : 0 : 0  
(Travelling Expenses, if any, £ )

Committee's Minute 12<sup>th</sup> June 1874

Character assigned A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

180-154001



*Autograph*

REPORT OF SURVEY FOR REPAIRS &c.



© 2019

Lloyd's Register  
Foundation