

REPORT of SURVEY for REPAIRS, &c.

No. in
Reg. Book.
110

No. 24302

Survey held at Liverpool Date, first Survey 27 June Last Survey 4 July 1874

on the Iron Bst "Laura"

Master Severina

Tonnage 492

built at Sunderland

When built 1870-3 mo

By whom built Pile

Owners Still

Port belonging to Plymouth

Destined Voyage Africa

If Surveyed Afloat or in Dry Dock Queens dry dock & Afloat

Last Survey, No. 7866

Port Liverpool

Classed

Years assigned.

Character in Register Book

A 1
70

REPAIRS, OR EXAMINATION AS PER RULE

Feeling equal to two strakes lifted all fore and aft on each side, examined and found good

Cause of Repairs to be clearly stated.

Present Condition of the
Decks

Good

Treenails

Good

Windlass and Capstan

Good

Waterways

Breasthooks and Stems

Pumps 2 ho

Comings

Transoms, Pointers, and Crutches

Boats 3 ho

Upper Deck Beams & Fastenings

Timbers of the Frame at the openings

Masts, Yards, &c.

Lower Deck Beams & Fastenings

Ditto Ditto at other places

Condition, how ascertained

Planksheers

Keelsons

Sails

Sheerstrakes

Ceiling

Anchors No. of 3 B. 15 & 2 K

Topsides

Rudder

Cables part seen Good

Wales

Copper Cement When put on 1870

Hawsers and Warps 4 ho

Plank (Bottom) and Counter

Caulking of

Standing & Running Rigging

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

She is now in good condition and in my opinion may continue as Classed and marked S.B. No 1-74.

The Amount of Entry Fee£

received by me, Wm

Special£ 3 : 3

26/8 1874

Certificate (if required)£

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

Liverpool 28th August 1874
A 1 - S.B. No 1-74

Will. C. Davey
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
Foundation

IRON 458-0222

"Laira"

24302



© 2019

Lloyd's Register
Foundation