

13713

REPORT of SURVEY for REPAIRS, &c.

No. in
Reg. Book.

No. 24432 Survey held at Liverpool Date, first Survey 16th Oct^r Last Survey 24th Nov^r 1874

on the Iron S. Rutlandshire Master A Jarvis

Tonnage 1057 built at Birkenhead When built 1863 - 8 mo

By whom built Clover Owners C. F. Ellis

Port belonging to London Destined Voyage San Francisco

If Surveyed Afloat or in Dry Dock Canning dry dock & afloat

Last Survey, No. 110218 Port Liverpool

Classed *A1-73
S. S. Div No 2-73

REPAIRS, OR EXAMINATION AS PER RULE

Rudder hanging repaired, bottom
repainted

Cause of Repairs to be clearly stated.

Present Condition of the
Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Good

Freemasts

Ribs

Good

Windlass and Capstan

Good

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper Cement When put on 1863

Caulking of

Bottom, Deck, & Waterways

Good

Pumps Main Belge

Boats 4 ho (new)

Masts, Yards, &c.

Condition, how ascertained Seen from deck

Sails one set new

Anchors No. of 3 B - 1 S - 1 K

Cables part seen Good

Hawsers and Warps 3 ho new

Standing & Running Rigging Good

Cargo and Main Hatchways Good

Hatches Good

She is now in good condition and
in my opinion may continue as Class

The Amount of Entry Fee £

Special £

Certificate (if required) £

(Travelling Expenses, if any, £)

Committee's Minute Liverpool, 22nd Decemb^r, 1874

Character assigned

A1 - Record Change of Owners

3

received by me,

24/12 1874

Blm^r Will^m C. Davey

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
Foundation

120N459-0304

Rutlandshire
24432



© 2019

Lloyd's Register
Foundation