

13875

# REPORT of SURVEY for REPAIRS, &c.

Damage

Rev 28/1/75

No. in Reg. Book. **No. 4341** Survey held at Kull Date, first Survey 10<sup>th</sup> Nov 74 Last Survey 18<sup>th</sup> Jan 75 1875

**53** on the Jon. Lt. Sct. Jaimis Master Oliver

Tonnage 317 built at Stockton When built 1860

By whom built Richardson Owners Rawson & Co

Port belonging to Kull Destined Voyage Rouen

If Surveyed Afloat or in Dry Dock In various dry dock & afloat in Lyons & Amsterdam &c

Last Survey, No. 11580 Port Lyon

|         |                 |                             |
|---------|-----------------|-----------------------------|
| Classed | Years assigned. | Character in Register Book. |
|         |                 | <u>6.43</u>                 |

REPAIRS, OR EXAMINATION AS PER RULE Damage &c SS No 1.73

Through striking of iron rivets  
Plating cut out at stems from lower part of stem upwards,  
Stems removed set fair & replaced fore lengths of plating  
Each side of stem set fair and six broken plates renewed  
Fore frame cut out set fair & replaced Breasthook when  
removed replaced  
Renewed deck planks on each side of main hatchway  
forward from front of bridge with pitch pine & caulked  
Bottom cleaned & painted

Cause of Repairs to be clearly stated.

|  |                                       |                                      |                      |   |
|--|---------------------------------------|--------------------------------------|----------------------|---|
| Present Condition of the Decks <u>plty new</u> | <u>good when new</u>                  | <u>Rivets</u>                        | <u>good when new</u> | Windlass and Capstan <u>work good</u>     |
| Waterways                                      |                                       | Breasthooks and Stems                |                      | Pumps <u>good</u>                         |
| Comings  |                                       | Transoms, Pointers, and Crutches     |                      | Boats <u>3 in 12 good</u>                 |
| Upper Deck Beams & Fastenings                  |                                       | Timbers of the Frame at the openings |                      | Masts, Yards, &c. <u>good</u>             |
| Lower Deck Beams & Fastenings                  |                                       | Ditto Ditto at other places          |                      | Condition, how ascertained <u>inspury</u> |
| Planksheers                                    |                                       | Keelsons                             |                      | Sails <u>good &amp; sufficient</u>        |
| Sheerstrakes                                   |                                       | Clamps and Shelves                   |                      | Anchors No. of <u>3 B and 1 Stepan</u>    |
| Topsides                                       |                                       | Ceiling                              |                      | Cables <u>good &amp; sufficient</u>       |
| Wales  |                                       | Rudder                               |                      | Hawsers and Warps <u>good</u>             |
| Plank (Bottom) and Counter                     |                                       | Copper When put on                   |                      | Standing & Running Rigging <u>good</u>    |
| Engine Room Skylights <u>good</u>              | Caulking of                           | Cargo and Main Hatchways <u>good</u> |                      |   |
| Coal Bunker, Openings, Lids, &c. <u>good</u>   | Bottom, Deck, & Waterways <u>good</u> | Hatches <u>good</u>                  |                      |   |
| General Observations, Opinion as to Class, &c. | Scuppers <u>good</u>                  |                                      |                      |   |

Is eligible in my opinion to remain as classed &c

The Amount of Entry Fee ... ..£ 1 : - : - received by me, Mr Davidson  
 Special ... ..£ 2 : 2 : - 20<sup>th</sup> Jan 1875  
 Certificate (if required) ... ..£ : : :

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 29<sup>th</sup> January 1875

Character assigned Fe 1

Dec 75  
J.P.W.



© 2019  
 Lloyd's Register  
 Foundation  
 IRON 460-0112