

14663

REPORT of SURVEY for REPAIRS, &c.

No. in
Reg. Book.
50

No. 5

Survey held at New York

Date, first Survey

Nov 4th

Last Survey

November 14 1874

on the Iron Steamship "Earl of Londale" Master

Rogers

Tonnage 1542 built at North Shields

When built 8 month 1871.

By whom built Smith

Owners Elliot & Co

Port belonging to Newcastle

Destined Voyage

If Surveyed Afloat or in Dry Dock in Dry Dock

Last Survey, No.

13810

Port

Iron

Classed

Years assigned.

Character in Register Book.

90. A.1.

4 mo. 1874

Lev. 1.35

REPAIRS, OR EXAMINATION AS PER RULE

The "Earl of Londale" was put on the Dry Dock Nov 4th 1874, and lowered Nov 20th 1874. The lower part of stem and forward end of keel, and six sheets of outside plating on each side were damaged and broken, also the heels of eight frames, caused by her being ashore on the rocks. See letter 26th December 1874.

The repairs were done by experienced mechanics, and to my entire satisfaction

See letter to Mr Leary Jan 9 75

Present Condition of the

Decks	Good	Treenails	_____	Windlass and Capstan	good
Waterways	Do	Breasthooks and Stemson	_____	Pumps	Do
Comings	Do	Transoms, Pointers, and Crutches	_____	Boats	Do
Upper Deck Beams & Fastenings	Do	Timbers of the Frame at the openings	_____	Masts, Yards, &c.	Do
Lower Deck Beams & Fastenings	Do	Ditto Ditto at other places	_____	Condition, how ascertained	from Deck & examination
Planksheers	_____	Keelsons	good	Sails	good
Sheerstrakes	_____	Clamps and Shelves	_____	Anchors	No. of good & sufficient
Topsides	_____	Ceiling	good	Cables	Do
Wales	_____	Rudder	Do	Hawsers and Warps	Do
Plank (Bottom) and Counter	_____	Copper	_____ When put on _____	Standing & Running Rigging	good
Engine Room Skylights	good	Caulking of	_____	Cargo and Main Hatchways	good
Coal Bunker, Openings, Lids, &c.	good	Bottom, Deck, & Waterways	_____	Hatches	good
General Observations, Opinion as to Class, &c.					

The Amount of Entry Fee ... £

received by me,

Registering repairs

£ 7 : 0 : 0

(Travelling Expenses, if any, £)

Committee's Minute

£ 10 : 0 : 0

Character assigned

90 F

Sep 74

James P. Leary
Surveyor to Lloyd's Register of British and Foreign Shipping.

Port of New York

Lloyd's Register
Foundation

IRON462-0026