

15676 35219
REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at London Date, first Survey Dec 8/75 Last Survey Jan 4th 1876
58 on the S Tantallon Castle Master Muir
TONNAGE under Tonnage Deck 985 Built at Greenock When built 1865 3
Ditto of Spar Deck, or Avoning Deck
Ditto of Poop, or Raised Qr. Dk.
Ditto of Houses on Deck Owners Cornie & Co Port belonging to Liverpool
Ditto of Forecastle
Gross Tonnage 1057 Residence
Crew Space, as per Rule By whom built Steele Destined Voyage San Francisco
Register Tonnage, cut on Beam
Engine Room If Surveyed Afloat or in Dry Dock Dry Dock
Reg. Tons as St^rmer, cut on Bm.

Length of Poop 40 ft. Ditto, Forecastle 38 ft. Ditto, Raised Quarter Deck 11 ft. Years assigned. Character in Register Book.
a deck House attached to Poop 47 feet in all - Classed A1 1174
Last Survey, No. 3802 Port Iron 88 Liv Nov 73

REPAIRS, OR EXAMINATION AS PER RULE

at the present time the vessel placed in dry dock the bottom scraped Painted &c.
Orany to damage the plates on the upper part of the main stem uninvolved in order to give the stem (being much bent) to make it fair, two the plates on each side renewed, New Figure Head Rails &c

Present Condition of the

Decks	Good	Greenails	Rivets	Good	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson		"	Pumps	
Comings	"	Transoms, Pointers, and Crutches		"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		"	Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Condition, how ascertained	and
Planksheers	"	Keelsons		"	Sails	sufficient
Sheerstrakes	"	Clamps and Shelves		"	Anchors No. of 3 Birs. 2 1/2 Tons	when
Topsides	"	Ceiling		"	Cables	they
Wales	"	Rudder		"	Hawsers and Warps	could be
Plank (Bottom) and Counter	"	Copper Painted When put on	Now	"	Standing & Running Rigging	seen
Engine Room Skylights	Good	Caulking of		"	Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good	"	Hatches	Good
Scuppers	Good			"		

General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as classed

Leahouse Martindale

The Amount of Entry Fee ... £ 2 : 2 : 0 received by me, } 7/6
Special ... £ 2 : 2 : 0 15 Jan 1876
Certificate (if required) ... £ 5 : 0 : 0
(Travelling Expenses, if any, £)

Committee's Minute 14th January 1876

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON464-0418