

Change of Owners. 15803 43295
REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at London Date, first Survey Jan 7 5 Last Survey July 7 1876
695 on the BK Broughton Master Mrs Beran
TONNAGE under Tonnage Deck 562.10 Built at Belfast When built 1868
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk. 22.54 Owners William Thomas Port belonging to Swansea
Ditto of Houses on Deck 12.78 Residence
Ditto of Forecastle 2.45
Gross Tonnage 599.88 By whom built Harland Destined Voyage South America
Crew Space, as per Rule 28.89 If Surveyed Afloat or in Dry Dock Pontoon
Register Tonnage, cut on Beam 570.88
Engine Room
Reg. Tons as St' mer, cut on Beam

Length of Poop ✓ ft. Ditto, Forecastle Monkey ft. Ditto, Raised Quarter Deck to Post 38 ft. Years assigned Classed AV 10.74 Character in Register Book.
Last Survey, No. 15520 Port Iron S.S. No. 1.72

REPAIRS, OR EXAMINATION AS PER RULE

At the present time the vessel placed
on the Pontoon and the bottom sighted.
owing to damage New Mizenmast of Wood.

Present Condition of the

Decks <u>Good</u>	Trunnels <u>Good</u>	Windlass and Capstan
Waterways <u>✓</u>	Breasthooks and Stemson <u>✓</u>	Pumps
Comings <u>✓</u>	Transoms, Pointers, and Crutches <u>✓</u>	Boats
Upper Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame at the openings <u>✓</u>	Masts, Yards, &c. <u>new</u> <u>Good</u>
Lower Deck Beams & Fastenings <u>✓</u>	Ditto Ditto at other places <u>✓</u>	Condition, how ascertained <u>and</u>
Planksheers <u>✓</u>	Keelsons <u>✓</u>	Sails <u>sufficient</u>
Sheerstrakes <u>✓</u>	Clamps and Shelves <u>✓</u>	Anchors No. of 3 Bros. & 1 Rdy <u>where</u>
Topsides <u>✓</u>	Ceiling <u>✓</u>	Cables <u>they</u>
Wales <u>✓</u>	Rudder <u>✓</u>	Hawsers and Warps <u>can be</u>
Plank (Bottom) and Counter <u>✓</u>	Copper <u>When put on</u> <u>✓</u>	Standing & Running Rigging <u>seen</u>
	Caulking of	
Engine Room Skylights <u>✓</u>	Bottom, Deck, & Waterways <u>Good</u>	
Coal Bunker, Openings, Lids, &c. <u>✓</u>	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Hatches</u>

General Observations, Opinion as to Class, &c.

She is now in an efficient state
of repair and entitled to remain as classed.

Senhouse Martindale

The Amount of Entry Fee ... £ : : received by me, } FL
Special ... £ 1 : 1 : 16 Feb 1876
Certificate (if required) ... £ : 5 :
(Travelling Expenses, if any, £)

Committee's Minute 18th February 1876

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
© 2019
Lloyd's Register
Foundation

IRON465-0074