

Iron. 15836

# REPORT of SURVEY for REPAIRS, &c.

No. in  
Reg. Book.  
313

No. 11339 Survey held at Sunderland Date, first Survey 4<sup>th</sup> February Last Survey 4<sup>th</sup> February 1876  
on the Iron S.S. William Hunter Master T. Jones

Tonnage 493 built at Newcastle When built 1865 (2.11.61)

By whom built Palmer Owners J. Johnsson

Port belonging to London Destined Voyage Coasting

If Surveyed Afloat or in Dry Dock Messrs S.P. Austin's Dry Dock

Last Survey, No. 14642 & 1113

Port Sunderland Iron

Classed

Years  
assigned.

Character in Register Book.

90. A. I.

(S.S. Sld. 22.2-1874)

2/75

REPAIRS, OR EXAMINATION AS PER RULE

Work done:- Lighted the bottom - scraped, cleaned and painted  
it with Zinc paint. - Repaired a small quantity of chain  
rail and Berthing.

Present Condition of the

Deck

Waterways } Good

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Plank sheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Good  
Greenalls

Breasthooks and Stems

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper Paint When put on

Caulking of

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Good

Not seen

Good

Do

Not seen

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

The Amount of Entry Fee ...

Special ...

Certificate (if required) ...

(Travelling Expenses, if any, &c.)

Committee's Minute

Character assigned

received by me,

187

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register  
Foundation

IRON465 - 0136