

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 4399** Survey held at **Dumbarton** Date, first Survey **20th Feb^r** Last Survey **27th Feb^r** 18**77**
 on the **Iron Steamer "India"** Master **—**
 TONNAGE under Tonnage Deck **1322** Built at **Dumbarton** When built **1871** 12
 Ditto of Spar Deck, or Awning Deck Owners **Portuguese Insurance** Port belonging to **Tisbon**
 Ditto of Poop Residence **—**
 Ditto of Gr. Deck By whom built **W. & J. G. & Co.** Destined Voyage **—**
 Ditto of Mastle If Surveyed Afloat or in Dry Dock **W. Williams dry dock and afloat**
 Ditto of St. mer, cut on Bm. **220**
 Poop **—** ft. Ditto, Forecastle **—** ft. Ditto, Raised Quarter Deck **—** ft.
 Survey, No. **14845** Port **Iron** Classed **10141**
 Character in Register Book **6.73.**

REPAIRS, OR EXAMINATION AS PER RULE

As this vessel was in the hands of Messrs W. & J. G. & Co. for some repairs to her machinery their attention was directed to the survey No. 1. then due. (See copy of letter and journal report in vessel. Glasgow No. 4066.) A verbal reply was given that the owners did not entertain the subject of class. I understand she will presently return for new boilers. Lighted the bottom in graving dock.

See letter 20 May '75
 attached to report No. 4066 dated 24 June '75

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations, Opinion as to Class, &c.

Under the above circumstances I respectfully leave the matter to the consideration of the Committee.


The Amount of Entry Fee ... £ 4 : 4 : received by me, }
 Special ... £ 187 - }
 Certificate (if required) ... £ : : :
 Travelling Expenses, if any, £

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

Character assigned

16th March 1877
 22nd March 1877
 Expunge from Book
 Gen Com. 20/3/77



© 2019

Lloyd's Register Foundation

IRON 470-0412