

# Report of Survey for Repairs of Engines and Boilers.

(Rev 26/3/99)

189

Survey held at *Hamburg*

Date, first Survey *16 March* Last Survey *20 March 1877*

on the *Iron Screw Steam vessel "Galatea", Capt. Böhm* Tons *1290*

ers *Deutsche Dampfschiffs Rhederei* Port belonging to *Hamburg*

Classed *100 A1*  
Years assigned *4.73*  
Character in Register Book.

diameter of Cylinders *30" & 60"*

Length of Stroke *4'-0"*

Pressure of Steam *60 lbs*

Indicated Horse Power *300*

Engines made at *Renfrew*

When made *1872*

By whom made *Hunterson & Coulborne & Co.*

## Particulars of Repairs and Examination :

The only repairs found necessary and which have been carried out are that a new propeller has been put on and a new white metal bush fitted into the after end of the stern tube. The shafting being in good condition also the cylinders, slide valves, pistons, guides & pumps which were all properly cleaned and readjusted were found necessary. The Engines and Boilers have had a thorough overhaul last year at Messrs Loebnitz Coulborne & Co Renfrew and are therefore at present in good and safe working condition.

The Amount of Fee ... £ *10 - 0 - 0* received by me,  
Certificate (if required) ... £ : : 187

(Travelling Expenses, if any, £ )

Committee's Minute

18

*Ernst Voss*  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register  
Foundation