

# Report of Survey for Repairs of Engines and Boilers.

No. 35

No. in  
Reg. Book.

Survey held at

Hull & Goole

Date, first Survey

8<sup>th</sup> of January

Last Survey

28<sup>th</sup> of September

1877

56

on the

Iron Screw Steamer *Zaimis*

Master

*Wilkinson*

Tons

317  
226

Owners

*Rawson & Robinson*

Port belonging to

*Hull*

Classed

Years  
assigned.

Character in Register Book.

A1  
175

Diameter of Cylinder

4 cyl. 12" x 24"

Length of Stroke

26"

Engines made at

*Hull*

When made

1869.

Pressure of Steam

66 p.s.i. inch

Registered Horse Power

60

By whom made

*Gilbert & Cooper*

## Particulars of Repairs and Examination

The old cylinders taken out and two new ones 17" x 34" dia. put in. - New pistons, slide valves, link motions, eccentrics fitted. - New barrel and bucket to airpump and new brass liner to circulating pump fitted. - New peacocks, new propellershaft and propeller supplied. -

New boiler made and fitted in accordance with Society's Rules.

Is in my opinion eligible to have the notification Lloyd's M.C. in the Registerbook.

The Amount of Fee ...

£ 3 : 3 :-

received by me,

Certificate (if required) ...

£ - : - :-

27<sup>th</sup> Sept 1877

(Travelling Expenses, if any, £ 1. 1. 0)

Committee's Minute

2nd October,

1877.

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

*A. Keydell*



Lloyd's Register  
Foundation

IRON474-0115