

REPORT of SURVEY for REPAIRS, &c.

No. in Book. **No. 11,643** Survey held at Sunderland Date, first Survey March 15th Last Survey 11th April 1877
 on the Steamer "Medusa" Master H. Wright

TONNAGE under Tonnage Deck
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St^rmer, cut on Bm.

Built at Sunderland When built 1862 7^{mo}
 Owners J. Laing Port belonging to Sunderland
 Residence Deptford Yard Sunderland
 By whom built J. Laing Destined Voyage Deptford Dry Dock
 If Surveyed Afloat or in Dry Dock

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
 t Survey, No. 20569 11523 Port Sunderland how
 Classified 90A1 5.76
 Years assigned. 3 76
 Character in Register Book. 90A1 5.76

IS, OR EXAMINATION AS PER RULE Annual Survey

Damage Renewed the following viz.
 the Propeller frame and Rudder, the four plates on each side forming the after hoods at the keel of the Vessel, one counter and three Stern plates, repaired two stern frames and Caulked the upper Deck throughout.
 Sighted the Bottom, cleaned and payed the same with two coats of lead.

Present Condition of the	Good.	Needle Rivets	good	Windlass and Capstan	good
Decks		Breasthooks and Stemson	"	Pumps	"
Waterways	"	Transoms, Pointers, and Crutches	"	Boats	three
Comings	"	Frames of the Frame at the openings	"	Masts, Yards, &c.	"
Upper Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	from Deck
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	"
Planksheers	"	Clamps and Shelves	"	Anchors	No. of 3 B. 18. 2K. good
Beerstrakes	"	Ceiling	"	Cables	"
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper paint When put on	now	Standing & Running Rigging	good
Plank (Bottom) and Counter	"	Caulking of	"	Cargo and Main Hatchways	good
Engine Room Skylights	good	Bottom, Deck, & Waterways	good	Hatches	good
General Observations, Opinion as to Class, &c.					

She is now in good and efficient condition and fit in my opinion to remain as Classed viz. 90. A. 1

Damage Rep^d 3 3 0
 The Amount of Entry Fee ... £ 3 : 0 : 0 received by me, May 1877
 Special ... £ 1 : 1 : 0 2nd May 1877
 Certificate (if required) ... £ : :
 Travelling Expenses, if any, £ : :
 Committee's Minute 4th May 18 77

Joseph Keew.
 Surveyor to Lloyd's Register of British and Foreign Shipping.

Character assigned Deferred
 for fees due on report No. 11523 9.10.70
 4/5/77