

# REPORT

No. in  
reg. Book

201

**TONNAGE** *under Tonnage Deck*

*Ditto of Spar Deck, or Awning Deck*

*Ditto of Poop*

*Ditto of Raised Qr. Dk.*

*Ditto of Houses on*

*Ditto of Forec*

Gross Tonnage

Crew Space, as per Rule .....

Engine Room

Reg. Tons as St<sup>r</sup>mer. cut on Bm.

Length of Poop *✓* ft. Ditto, Forecastle *✓* ft. Ditto, Raised Quarter Deck *✓* ft. Years assigned. Character in Register Book.

Last Survey, No. 20360 Port Iron

REPAIRS, OR EXAMINATION AS PER RULE

At the present time owing to damage  
Renewed Starboard side one topside plate, one sheerstrake  
plate repaired & rivetted, one Main frame scuffed & buffed  
to it, one Reversed frame buffed & scuffed, Iron Moulding, rivetted.  
2 Bottom ceiling Planks.

Portside one Inside Plate 2 Frames Scarphed & Broth Stuffed  
2 Reversed Frames Broth Stuffed. 1 Broth Stuffed & Inside Plate.  
Iron Moulding rivetted. 3 Batten ceiling Planks one New Boat.

This is a peculiar case of Damage. She is a Spar Deck Vessel. I had little cargo between decks. A Spare Screw<sup>+</sup> Propeller being lashed abaft the Foremast broke adrift in a gale with a heavy cross Sea & drove its blades through the Starboard side <sup>outside</sup> plating, and then through the outside plating on the Portside fixing itself in the side. & the Hands stopped the hole with canvas from the inside. (The main deck being Iron it formed a "Skating Rink" in the Propeller.

Decks	Freeneails	Rivets	Windlass and Capstan
Waterways	Breasthooks and Stemson		Pumps
Comings	Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings		Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places		Condition, how ascertained
Planksheers	Keelsons		Sails
Sheerstrakes	Clamps and Shelves		Anchors No. of
Topsides	Ceiling		Cables
Wales	Rudder		Hawsers and Warps
Plank (Bottom) and Counter	Copper	When put on	Standing & Running Rigging

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.

She is now in an efficient-state of repair  
and entitled to remain as before.

Senhouse Martindale

Samay Lee B3-3-0 <sup>Pa</sup> 30/1/76

The Amount of Entry Fee ... .. £   "   :   "   :   "   received by me, )

Special ... £ 3 : 3 : " 187

Certificate (if required) ... ..£

(Travelling Expenses, if any, £

Committee's Minute

*Character assigned*

with last London Report

*Surveyor to Lloyd's Register of British and Foreign Shipping.*

© 2019

Lloyd's Register  
Foundation

IRON 477-0405