

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. 115 No. 133 Survey held at Calcutta Date, first Survey 5th Feb^y 78 Last Survey 12th Feb^y 1878
 on the ship "Nelson" Master Christian
 Tonnage 1248 built at Port Glasgow When built 1862
 By whom built Hill Owners B. Ship Owners Co^y Ltd
 Port Belonging to X Liverpool Destined Voyage Uncertain
 If surveyed Afloat or in Dry Dock both
 Last Survey, No. 18211 Port Shields Iron Classed S.S. No 3-74
 Years assigned 4.77 Character in Register Book *A1

REPAIRS, OR EXAMINATION AS PER RULE.

This vessel having been placed in dry dock to undergo examination according to Special Periodical Survey No. 1 of the rules has had her bottom scraped, cleaned and well coated with paint - she has also been cleaned and painted out inside, the ceiling equal to one stroke fore and aft on each side has been removed and the cement being found firmly adhering to the iron and in good preservation has not been disturbed - The rudder hangings have been rebushed, the decks are in sufficiently good condition to allow of the voyage being completed, but the old part should be examined on arrival of the vessel at Home.

Present Condition of the			
Decks	good where seen for the present	Treenails	Rivetting good where seen
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"
Planksheer	plating	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	good & well hung
Plank (Bottom) and Counter	"	Copper	Paint When put on Feb ^y 78.
		Caulking of	
		Bottom, Deck, & Waterways	good
Engine Room Skylights	Good Bunkers, Openings, Lights, &c.	Scuppers	good
		Cargo and Main Hatchways	good
		Hatches	good.

General Observation, Opinion as to Class, &c. A strong well built iron vessel has been well kept and is hereby recommended credit for Special Survey No. 1 of the rules.

Mem 19/3/78 The Governing Committee consider that the record of S.S. No. 133 should be not be delayed until the removal of decks as the S.S. has been held.

The Amount of Entry Fee ... £ 3 : : received by me, }
 Special ... £ 5 : 9 : 4 £ 8. 14. 4. 187 }
 Certificate if (required) ... £ 0 : 5 : 0 (to be sent to the owner at Home)
 (Travelling Expenses, if any, £)
 Committee's Minute 19th March 1878.
 Character assigned *A1

M. Stewart R.N.R.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Port of Calcutta
 The 22nd February 1878.

L. H. Lur Cal 25/3/78

S.S. No 1-78



© 2019

Lloyd's Register Foundation