

REPORT of SURVEY for REPAIRS, &c.

No. *SS No 2* 21514. 37.410
 Survey held at *London* Date, first Survey *July 8th* Last Survey *Aug 9th* 1878
 Reg. Book. *335* on the *S Jessie Readman* Master *Kennedy*
 Tonnage under Tonnage Deck *898* Built at *Greenock* When built *1865* 11
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage *1013* Owners *Albion Sh Co* Port belonging to *Glasgow*
 Crew Space, as per Rule
 Register Tonnage, cut on Beam *962* Residence
 Engine Room By whom built *Scott* Destined Voyage
 Reg. Tons as St'mer, cut on Bm. If Surveyed Afloat or in Dry Dock *Dry Dock*

Length of Poop *38* ft. Ditto, Forecastle *37* ft. Ditto, Raised Quarter Deck *ft.*
 Last Survey, No. *18961* Port *Iron* Classed *A* 6.77
 SS *Sen M 174*

REPAIRS, OR EXAMINATION AS PER RULE *SS No 2*

At the present time placed in Dry Dock
 the timbers and ceiling in the bottom equal to
 three strakes on each side taken up exposing both
 surfaces of plating, examined and found good cement
 tested which was adhering firmly to the iron and
 thickened where required.

Bottom & Scraped and coated.
 Chain cables ranged on deck and examined 300 Fathom
 Iron Patent purchase *Windlop*.

Present Condition of the

Decks	Treenails	Rivet	Windlass and Capstan
Waterways	Breasthooks and Stemson		Pumps
Comings	Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings		Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places		Condition, how ascertained
Planksheers	Keelsons		Sails
Sheerstrakes	Clamps and Shelves		Anchors No. of 3 Bows, 2 K'dys
Topsides	Ceiling		Cables complete 300 Fathom
Wales	Rudder		Hawsers and Warps
Plank (Bottom) and Counter	Copper Coated When put on		Standing & Running Rigging
Engine Room Skylights	Caulking of		Cargo and Main Hatchways
General Observations, Opinion as to Class, &c.	Bottom, Deck, & Waterways		Hatches

Coal Bunker, Openings, Lids, &c. Scuppers

She is now in good condition and
 entitled to remain as classed and to be
 Marked *SS No 2-1878*.

Senhouse Martindale

The Amount of Entry Fee ... £ ... : : : received by me, }
12/8/78 Special ... £ 5 : 5 : : *1878*
 Certificate (if required) ... £ : 5 :
 (Travelling Expenses, if any, £)

Committee's Minute

13th August, 1878

Character assigned

SS No 2-78

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

120479-0339

Foundation