

* 22636

Report of Survey for Repairs of Engines and Boilers.

No. 26350

No. in Reg. Book. Survey held at

Liverpool
S.S. "Naples"

Date, first Survey 1st Jan'y

Last Survey 11th Jan'y 1879.

40 on the

Master Eaton

Tons 1473

Owners Nelson Docking Co

Port belonging to

London

Classed

Years assigned

Character in Register Book.

100 A 1.

Lloyd's M.C. 5th 1875

Diameter of Cylinders 1 of 36" 1 of 38"

Length of Stroke 45"

Engines made at

Shields

When made

YEAR.

1875.

Pressure of Steam 70

Registered Horse Power 250

By whom made

N. Eastern Marine & Co

Particulars of Repairs and Examination

The cylinder covers, valve casing doors, air, circulating pumps, and condenser opened out. The several parts examined and found good. Crank shaft examined and found in good order. Bilge suction pipes overhauled. A new propeller shaft has been fitted.

The boilers opened out examined and found fairly good. New funnel fitted to donkey boiler, steam which pipes renewed.

The machinery and boilers of this vessel are now in a good condition, and in my opinion entitle the vessel to retain the Lloyd's M.C. (in red).

The Amount of Fee ... £ : : received by me, Certificate (if required) ... £ : : 187

(Travelling Expenses, if any, £

Committee's Minute Liverpool Feb¹¹ 11-1879.

100 A 1.

J. G. Kinghorn

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

1000/1/8/76.

Mr. Thompson does not state why.
This survey was held, nor has he
charged any fees. Submitted
that he be asked to explain

MD

12-2-79

Dr. to Mr. Light, Liverpool

12/2/79

This survey appears
has been held in consequence of James
demanding to be submitted as James
also directed to MD 18-2-79

26352

ss

James



© 2019

Lloyd's Register
Foundation