

Report of Survey for Repairs of Engines and Boilers.

No. 160 (23701)
 No. in Reg. Book. 118 on the South Shields S.S. "Lens" Date, first Survey 17th April Last Survey 26th April 1879
 Master April

Built at Sunderland When built 9 mo 1872
 ns 803 Owners Turner & Co. Ltd. For Belonging to London Classified 2nd Years assigned. 90 Character in Register Book. A1
Last Survey 22536 Iron 1.79
 Diameter of Cylinders 24 + 51 Engines made at Sunderland When made 1872
 Length of Stroke 33 Pressure of Steam 65 lb By whom made J. Dickenson
 Registered Horse Power 90

Particulars of Repairs and Examination. The Machining of this Vessel damaged as per damaged Report of 9th May 1879 has been made good and efficient. New steel propeller blade fitted, adjacent blade taken off. Steel bolts examined & new bolts fitted propeller securing nut tightened up, the Machining otherwise appears generally in good order, and this Vessel is now eligible to return this class as notified in the Society Register Book.

(Condition of Engines and Boilers, and subsequent Repairs and Examinations)

(Travelling Expenses, if any, £)

Damage Survey
 The Amount of Fee ... £ 1 : 1 received by me, A. Young
 Certificate (if required) ... £ 24 July 1879
 Committee's Minute

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



The making of the record L. Ben
indicated and confirmed after being
presented and is now reported to
be an good working condition
but further that also is desirable
to remain in closed-

MD 27.5.29



© 2019

Lloyd's Register
Foundation