

#24652

# Report of Survey for Repairs of Engines and Boilers.

(No. 23.9.79)

No. in Reg. Book. *Survey held at* London *Date, first Survey* 11<sup>th</sup> Aug. *Last Survey* 12<sup>th</sup> Sept 1879

*on the* S.S. "Hankow" *Master* Symington

*Built at* Newcastle *When built* 1843 - 8 mo.

*Tons* 2332 3594 3153 *Owners* Watts, Milburn *Port belonging to* London *Classed* Lloyd's M.C. 12-76 *Character in Register Book.* 100A1 *Years assigned.* 2-79 *YEAR.*

*Diameter of Cylinder* 52" + 96" *Engines made at* Newcastle *When made* 1843

*Length of Stroke* 56"

*Pressure of Steam* 40 lb *By whom made* A. & W. Hawthorn.

*Registered Horse Power* 450

## Particulars of Repairs and Examination

A new high pressure cylinder and slide valve has been fitted and tried under steam in accordance with recommendation contained in damage report dated 14<sup>th</sup> September, 1879.

The machinery of this vessel is now in good and efficient condition and it is submitted that she is eligible to remain as classed.

The Amount of Fee ... £3 0 0 received by me, 7 Oct 1879

Certificate (if required) ... £ : :

Travelling Expenses, if any, £

Committee's Minute 18

William Paisley  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register  
Foundation



23.9.79

Official condition and it is submitted that it is  
desirable to remain as closed.

The machinery of the vessel is now in good and  
19th September, 1947.

Recent work on the contract in connection with the  
has been fitted and tested under steam in accordance with  
A new high pressure cylinder and slide valve

*A. & M. MacArthur.*

*(Faint bleed-through from reverse side)*

100A  
8-76  
J.Y.

2.2 "Lantern"  
Lantern  
Date first Survey 11<sup>th</sup> Aug. Last Survey 12<sup>th</sup> Sept 1877  
Blairstown

Report of Survey for Repairs of Engines and Boilers