

ANNUAL SURVEYS.

26578

No. 59208 Survey held at London Date, first Survey 10 May Last Survey 10 May 1880
No. in on the Reg. Book. 1984 Tonnage 884 Built at Hartlepool Master Brown
By whom built 1879 Owners Clarke & Co
Port belonging to London Destined Voyage Coasting
If Surveyed Afloat or in Dry Dock Bridge dry dock

Last Survey, No. 24791 Port of Iron
Present Condition of the Decks Good Treennails Ribs Roofs
Waterways d° Breasthooks and Stemson d°
Comings d° Transoms, Pointers, and Crutches d°
Upper Deck Beams & Fastenings d° Timbers of the Frame at the Openings d°
Lower Deck Beams & Fastenings d° Ditto ditto at other places d°
Planksheers d° Keelsons d°
Sheerstrakes d° Clamps and Shelves d°
Topsides d° Ceiling d°
Wales d° Rudder d°
Plank (Bottom) and Counter d° Copper or Y.M. When put on -
Engine Room Skylights d° Coal Bunker, Openings, Lids, &c. d° Scuppers d°
General Observations, Opinion as to Class, &c. Bottom cleaned and recoated.
This vessel appears eligible to remain as classed

Committee's Minute Friday, May, 21st 1880
Character assigned 100A
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in on the Reg. Book. Master
Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock
Last Survey, No. Port of Classed
Present Condition of the Decks Treennails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways
General Observations, Opinion as to Class, &c. Hatches

Committee's Minute 18
Character assigned
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

Gracie



© 2019

Lloyd's Register
Foundation