

Report of Survey for Repairs of Engines and Boilers.

No. *5192* (Received at London Office, *18/10/80*)
 No. in Reg. Book. *377* Survey held at *Glasgow* Date, first Survey *29th July* Last Survey *8th Oct 1880*
 on the Machinery of the *S.S. "Bertha" (Donkey Boiler)* (Number of Visits *1*)
 Tonnage, Gross *398* Built at *Glasgow* When built *1864*
 Ditto, Net *251* Owners *N. L. Seligmann & Son* Port belonging to *Glasgow*
 Diameter of Cylinder *22" x 40"* Engines made by *Kincaid & Donald* When made *1874*
 Length of Stroke *27"* Boilers made by *"* When made *1874*
 Pressure of Steam *60* If Surveyed Afloat or in Dry Dock *afloat.* Years assigned *1* Character in Register Book *A 1*
 Registered Horse Power *70* Classed *1880*
 Last Survey No. *27217* Port *Iron*

Particulars of Repairs and Examination *A new Donkey Boiler having been made by Messrs. Ross & Duncan, Glasgow, in conformity with approved design, & tested according to Committee's requirements. It has now been fitted on board, & the safety valve tested under steam satisfactorily, as recommended in Glasgow Report No. 5103.*

General Observations, Opinion, and Recommendation:—*The Engines and Boilers are now in good order & safe working condition, and eligible in my opinion to be noted in the Register Book Lloyd's M.C. 5.80 (vide Glasgow Report 5703)*

Entry or Registering Fee *£ - : - : a*
 Survey Fee *£ 2 : 2 : a* received by me, *For J.B.*
 Certificate (if required) *£ 15 Oct. 1880*
 (Travelling Expenses, if any, £)

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute *Friday, October 22nd 1880*

Assigned

Lloyd's M 6-5.80

J.B.



Lloyd's Register Foundation

120 N495-0344

This submitted that this
was also now eligible
to have the notifica-
tion. See as he
5. 80 recorded in
the Register Book

M
18/10/80



© 2019

Lloyd's Register
Foundation

Product of the Lloyd's Register of Engineers and Boilers