

Lloyd's Register of British
and Foreign Shipping.

Hull. 8 May 1861

George Saffery Esq

Sir

With reference to my report No 3131
Screw Steamer "Albion" diagonal truss plates are
fitted on the upper deck at the Masts but
not continued forward and aft with the diagonal
truss

Mr Messrs Samuelson & Co making enquiry this
morning I informed them the classification had
been deferred, the Committee wishing to know if
additional longitudinal strength had been added
in consequence of the extra length,

They have sent a midsection which I enclose with
a letter I received from them.

I am Sir
Your Obedt Servant
Henry Adams